DPS-38-C (Rev. 07/*02)

State of Connecticut Department of Public Safety / Division of State Police State Police Troop: _G Case	ACCIDENT INFORMATION SUMMAR Number: DPS- 05027487 Notations: Traffic: L
	06/06/05 Time: 0559 hours Weather: C Lane 3 of 3 Direction of Travel: N S E (W
(Passenger Car, Truck, Bus, Etc.) Town / City: Stammford/135 Location	(Pedestrian, Pole, Bridge Abutment, Etc.) I-95 Westbound at exit 7
Utility Pole Name & Number (If Applicable):	Other (Specify):
0/ 0/ 25	Oper#2: Urgo, Robert J. DOB: 07-16-68 Gender: ►M □F
DOB: 04-24-35 Gender: ☆M □F Address: 256 Westland St.	
	Address: 465 Flax Hill Rd.
Town: Hartford State: CT Zip: 0611	
Oper. Lic. # 041567101 Type: AM State: CT	Oper. Lic. # 198093220 Type: 2 State: CT.
Owner#1: Cassirino Trucking Inc.	Owner #2: Same
Address: 330 Sullivan Ave. South Windsor, Ct.	
Registration Plate: 15789A State: Ct.	
Make: Ford Model: LTA9 Year: 199	3 Make: Lexus 4dr. Model: ES300 Tan Year: 1997
VIN: 1FTYY95R7PVA25613	VIN: JT8BF22G2V5005478
Seatbelt(s): Yes No Airbag: Yes (Deployed No N/A) Insurance Company: Insurance Policy #: Injuries: None Vehicle Damage: Rear-end Vehicle Towed: No Syes, Bills Occupant(s): [Name / DOB / Address / Position in Veh] NC-159157 DOT-219644 80,000	Insurance Company: Encompass Insurance Policy #: 261582602 Injuries: Neck
Oper#3: Vargas, Oscar	Oper #4:
DOB: 08-02-59 Gender: ☒ M ☐F	DOB: Gender:
Address: 2100 Writtier St.	Address:
Town: Rahway State: N.J. Zip: 07065	Town: State: Zip:
Oper. Lic. # V05816090008592 Type: State: N.J.	Oper. Lic. # Type: State:
Owner #3: Same	Owner #4:
Address: Same	
Registration Plate: AG397W State: N.J.	Address:
m m 1009	Registration Plate: State:
4 + m - 4 m m O = F = T = T = C = C = C = C = C = C = C = C	
Seatbelt(s): NYEYes No Airbag: Yes(Deployed NY NN NO NA Ace American Ins. Insurance Policy #: LMTH07939620 Injuries: None	VIN: Seatbelt(s): Yes No Airbag: Yes (Deployed Y N) No N/A Insurance Company: Insurance Policy #: Injuries:
Vehicle Damage: Tractor Damage	Vehicle Damage:
Vehicle Towed: ☐No [X]Yes, Bills Occupant(s): [Name / DOB / Address / Position in Veh]	Vehicle Towed: ☐No ☐Yes, Occupant(s): [Name / DOB / Address / Position in Veh]
Vargas, Daniel 05-16-96	Cookpain(a). [Hallie / DOD / Address / Fosition in Ven]

Brief Description of Accident

Vehicles 1,2 and3 were traveling I-95 westbound at exit 7 in the center lane. Vehicle 2 was traveling behind vehicle #1 and vehicle #3 was traveling behind vehicle #2. Operator #1 was slowing for a previous accident (see case # DPS-05027485) when vehicle #2 struck the rear of vehicle #1. Operator #3 also could not slow down in time and struck the rear of vehicle #2. Vehicle #3 then drove over the rear of vehicle #2 which pushed vehicle #2 under the rear of vehicle #1. All three vehicles came to final rest blocking all three westbound lanes. This case is still under investigation.

#1 Ambulance	X Yes, Company Stamford AMR No	#2 Ambulance	Yes, Company No
Patient Name:	Robert J. Urgo	Patient Name:	. 100
Hospital	Stamford	Hospital	
Injuries	Neck injuries	Injuries	-
#3 Ambulance	Yes, Company No	#4 Ambulance	Yes, Company No
Patient Name:		Patient Name:	·
Hospital		Hospital	v <u></u>
primi			
Injuries		Injuries	
Injuries	S: Do Not Release Unless Next of Kin		
Injuries FATALITIES		Notified	
Injuries FATALITIES Name	S: Do Not Release Unless Next of Kin	Notified Name	
Injuries FATALITIES Name Next of Kin Note	S: Do Not Release Unless Next of Kin	Notified Name Next of Kin Not	
Injuries FATALITIES Name Next of Kin Not Name	S: Do Not Release Unless Next of Kin	Name Next of Kin Not	ified?
Injuries FATALITIES Name Next of Kin Not Name Next of Kin Not	S: Do Not Release Unless Next of Kin	Name Next of Kin Not	ified?
Injuries FATALITIES Name Next of Kin Not Name Next of Kin Not ENFORCEM	S: Do Not Release Unless Next of Kin	Name Next of Kin Not Name Next of Kin Not	ified?